Qty:

Date:

Monday, 02/03/2009 2:35:39 PM

User:

Linda Lacelle

## **Process Sheet**

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number **Estimate Number**  : 46224

: 10804

P.O. Number

**Previous Run** 

: 02/03/2009 This Issue

: NC

Prsht Rev. First Issue

: // : 46223 Type

S.O. No. :

: MACHINED PARTS

: D27953

**Part Number Drawing Number** 

: D2795-3

: REWORK D2795-043

**Project Number Drawing Revision** 

**Drawing Name** 

Material

Due Date

: 09/03/2009

1 Um:

Each

Checked & Approved By

Comment

Written By

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

LARGE FAB 1 1.0

LARGE FABRICATION RESOURCE 1

Comment: LARGE FABRICATION RESOURCE 1

PULL FROM STOCK:

1 X D2795-043 B 45784

**REMOVE BUSHING - DISCARD** 

SAO 09-03-62

2.0

D2795043

Arm Assembly, LH



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Arm Assembly, RH



PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

RESTOCK UNDER P/N D2795-3

USING NEW B/N

4.0

QC21

FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion

inspect to correct step

Form: rprocess